

ACCEPTABLE PAINT SCHEMES

1. Starting at blade tip, paint the first 1/6th of the blade length with gloss white. Paint the second 1/6th length with yellow or orange. Paint the third 1/6th of blade length with gloss white. Paint the next 1/3rd of blade length with yellow or orange. Paint remaining 1/6th of the blade length with gloss white.

HUB

W	Y	W	Y	W		W	Y	W	Y	W
1/6	1/6	1/6	1/3	1/6		1/6	1/3	1/6	1/6	1/6

2. One black and one white blade (two-bladed rotor systems).
3. Paint schemes previously approved under a U.S. Forest Service or DOI AM contract.
4. High visibility paint schemes and color variations specified by manufacturer in a service bulletin, instruction, or other manufacturer-published document or text.